

## Assembly Instructions HB-CW

A-6pcs



10x40 mm

B1-4pcs



6x30 mm

B2-2pcs



6x40 mm

C-4pcs



5x100 mm

F-1pc



1pc



4pcs

**Attention:**

Product is made of high quality beech wood guaranteeing maximum resistance and long service life of the bench.


**Like all solid wood products it must not be left in areas of high humidity or damp that will cause natural movement.** Recommended humidity level max. 60%.

**Product has NO TREATMENT. Please treat your worktop with a varnish or oil before assembly including bottom of worktop.** Don't forget to repeat surface treatment each 6 months. This is especially important if situated in an unheated workshop, garage or outbuilding. Varnish (oil) prevents absorption of surrounding moisture.

Wood is a natural product, check and tighten all screws and bolts every 6 months.


To increase stability, the worktop can be screwed to a table.

**WARNING!!!** - In this case, the table top to which you will screw the worktop will be damaged!!!




A+F

Back leg without holes for spindle




Front leg with holes for spindle




Spindle "body"

B1

Spindle with guide rods



Vice jaw



A+F

B2

A+F

Before screwing of vice jaws, be sure that jaw is parallel with worktop .

**Hint:** Tighten jaws using spindles. Align jaws with bench top and then use B2 screws for attaching jaw to pindles.